

Safety Issues

The EA identified the following SH 402 corridor safety issues:

- Shoulders typically less than half as wide as the standard
- Numerous residential and business driveways contribute to traffic issues, especially near intersections
- Sight distance problems primarily due to local terrain

Projected increased traffic, combined with high speeds, unexpected stops, inadequate shoulders, and restricted or inadequate sight distances, make SH 402 a candidate for safety improvements.

Accident Types for SH 402 MP 0.00 - MP 4.23

